



Flatwork and Open Face Molds: Firing Deviation Factors

There are many reasons and factors for deviating from standard firing tables. A few common ones are outlined below.

Double the maximum finished glass thickness to slow down heating and cooling ramps:

Uneven load on refired slab: When frit or other components are mounded on a prefired slab

Thickness variations: When the maximum thickness of the design is more than twice the thinnest

Irregular edges: When the edges of the work are wavy, inconsistent, or have long tapered points

If your kiln has top elements only, and you want to fire over 1 inch / 25mm thick anyway

Heavy molds: When firing in molds over 2" thick, especially dense ones such as plaster

Add 50% to the maximum finished glass thickness for each factor listed below to slow down ramp rates:

(Add 100% when both factors apply):

Very full kiln: If the kiln is very full, and air circulation area is limited

Color variations: This guide is based on experience with works combining colors. However, for works containing strong colors or extreme color variation, slow ramp rates to an assumed 50% thicker rate.

To decrease devit or limit bubble rise: speed up the ramp-up rate from 1200F (649 C) to peak temp

Color variations:

To limit open bubbles on the top surface: If mold details are filling OK, simply decrease soak time at peak temperature. If mold details are not filling well, add to the soak at 100F/538C, and slow the ramp up to peak.

Drying plaster molds: Predry by ramping slowly to 200 F (93 C), holding, then continuing ramp to 600 F (316 C). This will drive out the moisture and minimize surface scum on the glass. If you must dry the mold during a glass firing, add a hold to your up-ramp at 200 F (93 C) to dry the mold. Vent the kiln until mold is dry. Larger molds require slower ramps and longer hold times.

When speed is important: Increasing speed from these recommendations is certainly possible in certain situations, such as faster heat ups for first firings of frit, for very small objects (under 6 inches/152 mm diameter), or for single color/consistent thickness/smooth edged shapes. The best procedure is to use caution when shaving time off any ramp: take small sequential steps, and test for success before investing a lot of time or materials into a final piece. Measure temp differentials between the immediate top and bottom of the work during annealing and cooling to determine a maximum ramp rate. A good rule of thumb is that there should be less than 10 °F (5.5°C) differential during annealing, and less than 20°F (11°C) differential during cooling ramps. If you record bigger differentials, choose slower ramp rates. Richard Whiteley's article and sketches on this topic in the 2008 GAS Journal are helpful.

ART GLASS

90 COE FUSIBLE

SYSTEM 96®